


SPECIAL AIRWORTHINESS INFORMATION BULLETIN

Aircraft Certification Service
Washington, DC



U.S. Department
of Transportation

**Federal Aviation
Administration**

No. CE-02-25
April 16, 2002

We post SAIBs on the internet at "av-info.faa.gov"

This is information only. Recommendations are not mandatory.

Introduction

This Special Airworthiness Information Bulletin (SAIB) advises you, owners/operators of Dornier 228 series airplanes, of issuance of Dornier Service Bulletin (SB) 228-235.

Background

The Small Airplane Directorate, Aircraft Certification Service, of the Federal Aviation Administration (FAA) issued Airworthiness Directive (AD) 2001-04-04 on February 28, 2001. This AD required the implementation of the provisions of Dornier All Operators' Telex AOT-228-30-022 to eliminate the overheating of windshield deicing spray nozzle heaters.

Dornier has now issued a Service Bulletin, SB 228-035 **to supersede** AOT-228-30-022.

Recommendations

Implementation of SB 228-235 is considered an acceptable Alternative Method of Compliance (AMOC) for AD 2001-04-04.

The Small Airplane Directorate issued a letter to docket 99-CE-99-AD that recognizes SB 228-235 as an approved alternate method of compliance (AMOC) for 2001-04-04. We have attached a copy of the AMOC letter to facilitate utilization.

The Service Bulletins Can Be Obtained From

Fairchild Dornier GmbH
PO Box 11 03
D-82230 Wessling
Germany
Phone: (011) 49 81 53-30 0
Fax: (011) 49 81 53-30 29 01

For Further Information Contact

Karl M. Schletzbaum, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 901 Locust Street, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090; email: karl.schletzbaum@faa.gov



U.S. Department
of Transportation

Federal Aviation
Administration

Memorandum

Subject: **INFORMATION**: Alternative Method of Compliance
(AMOC) for AD 2001-04-04

Date: APR 03 2002

From: Manager, Standards Office, ACE-110

Reply to: Karl Schletzbaum
Attn. of: 816- 329-4112

To: Docket 99-CE-99-AD

The Small Airplane Directorate issued Airworthiness Directive (AD) 2001-04-04 on February 8, 2001. This AD applied to Dornier Luftfahrt GmbH model 228-100, 228-101, 228-200, 228-201, 228-202 and 228-212 airplanes. The manufacturer subsequently issued Service Bulletin (SB) SB-228-235; Revision 1, dated December 18, 2001, which introduced a modification that replaces the requirements of the original applicable service information, All Operators Telefax (AOT) AOT-228-30-022. The AOT and AD 2001-04-04 required the deactivation of the windshield spray nozzle heating elements, service bulletin SB-228-235 allows the modification of the spray nozzle system instead.

Dornier service bulletin SB-228-235, Revision 1 is approved as an equivalent to Dornier All Operators Telefax AOT-228-30-022. Utilization of SB-228-235, Revision 1 is an approved AMOC for AD 2001-04-04 and is terminating action for this AD.

Michael K. Dahl